

Facility Summary in PARK County in the City of CLYDE PARK

Location: DALES FUEL INC
301 1ST AVE
CLYDE PARK, MT 59018 PARK

Sys Fac ID: 34-07600

Last Inspected On: 5/6/2013

Operating Permit Renewal Date: 6/15/2016

Contact: Dale Jones, (406) 686-4681

Owners/Operators: Dales Fuel Inc, Owner	(406)-686-4681	PO BOX 90 CLYDE PARK MT 59018
Dale Jones, Operator	(406)-686-4681	PO BOX 90 CLYDE PARK MT 59018-0090
Dale Jones, UST Class A Operator		
Dennis A Franks, UST Class B Global Operator		

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
5	16	4/1/1999	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
3991			Double-Walled	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Not Applicable
Gasoline			Manual Interstitial Monitor	Deferred	
6,000					
6	16	4/1/1999	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
3992			Double-Walled	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Not Applicable
Gasoline			Manual Interstitial Monitor	Deferred	
2,500					
7	16	4/1/1999	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
3993			Double-Walled	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Not Applicable
Diesel			Manual Interstitial Monitor	Deferred	
1,900					
8	16	4/1/1999	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
3994			Double-Walled	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Not Applicable
Diesel			Manual Interstitial Monitor	Deferred	
1,900					

Facility Summary in PARK County in the City of CLYDE PARK

Location: SHIELDS VALLEY HIGH SCHOOL
401 1ST ST E
CLYDE PARK, MT 59018 PARK
Contact: Bill Sarrazin, (406) 686-4621

Sys Fac ID: 34-12515
Last Inspected On: 3/29/2013
Operating Permit Renewal Date: 9/24/2016

Owners/Operators: School Dist Shields Valley, Owner (406)-578-2176 PO BOX 131
WILSALL MT 59086-0131
Dennis Kuhl, UST Class A Operator
William Sarrazin, UST Class A Operator
Darcy Street, UST Class A Operator
Dennis Kuhl, UST Class B Operator
Darcy Street, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	50	7/1/1965	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
2725			Lined Interior/Impressed Current	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Impressed Current
Diesel		3/29/2013	Automatic Tank Gauging 0.2	Not Listed	
8,000					

Facility Summary in PARK County in the City of COOKE CITY

Location: COOKE CITY EXXON
US HIGHWAY 212
COOKE CITY, MT 59020 PARK
Contact: Rick D Sommers, (406) 838-2244

Sys Fac ID: 34-01584
Last Inspected On: 6/3/2013
Operating Permit Renewal Date: 9/17/2016

Owners/Operators: Rick D Sommers, Owner (406)-838-2244 PO BOX 1128
COOKE CITY MT 59020-1128
Lucas Jack, UST Class A Operator
Marlo Pmarlof, UST Class A Operator
Rick D Sommers, UST Class A Operator
Lucas Jack, UST Class B Global Operator
Rick D Sommers, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
7	24	10/1/1991	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
757			None	None	Yes
Currently in Use		10/1/2001	Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		6/3/2013	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
6,000					
8	24	10/1/1991	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
758			None	None	Yes
Currently in Use		10/1/2001	Not Required	Safe Suction	Galvanic
Gasoline		6/3/2013	Automatic Tank Gauging 0.2	Deferred	
6,000					
9	18	10/1/1997	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
759			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Diesel		6/3/2013	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
5,000					
10	18	10/1/1997	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
760			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		6/3/2013	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
10,000					

Facility Summary in PARK County in the City of COOKE CITY

Location: NORTHEAST ENTRANCE GAS PUMPS

Sys Fac ID: 34-08869

COOKE CITY, MT 59020 PARK

Last Inspected On: 5/21/2013

Operating Permit Renewal Date: 9/26/2016

Contact: Tim Hudson, (307) 344-7381

Owners/Operators: National Park Service, Owner (307)-344-2333 PO BOX 168
YELLOWSTONE NATIONAL PARK WY 82190-0168

Harry Laney, UST Class A Operator
Claude W Long, UST Class A Operator
Harry Laney, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	23	8/1/1992	Cathodically Protected Steel	Steel	Flapper Valve (Auto Shutoff)
1741			Double-Walled	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		5/21/2013	Continuous Interstitial Monitor	Deferred	
2,000					
2	23	8/1/1992	Cathodically Protected Steel	Steel	Flapper Valve (Auto Shutoff)
1742			Double-Walled	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Diesel		5/21/2013	Continuous Interstitial Monitor	Deferred	
2,000					

Facility Summary in PARK County in the City of COOKE CITY

Location: COOKE CITY SINCLAIR AND CABINS
115 MAIN ST
COOKE CITY, MT 59020 PARK

Sys Fac ID: 34-10046

Last Inspected On: 6/3/2013

Operating Permit Renewal Date: 9/17/2016

Contact: Lucas Jack, (406) 838-2000

Owners/Operators: Rick D Sommers, Owner

(406)-838-2244

PO BOX 1128

COOKE CITY MT 59020-1128

Lucas Jack, UST Class A Operator

Rick D Sommers, UST Class A Operator

Lucas Jack, UST Class B Global Operator

Rick D Sommers, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
6	17	10/1/1998	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
3670			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Continuous Interstitial Monitor	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor, MLLD Line Tightness Testing	
8,000					
7	17	10/1/1998	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
3671			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Continuous Interstitial Monitor	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor, MLLD Line Tightness Testing	
8,000					

Facility Summary in PARK County in the City of EMIGRANT

Location: EMIGRANT GENERAL STORE
3 MURPHY LN
EMIGRANT, MT 59027 PARK
Contact: Bert Otis, (406) 333-4434

Sys Fac ID: 34-06713
Last Inspected On: 5/16/2013
Operating Permit Renewal Date: 7/8/2016

Owners/Operators: Bert Otis, Owner (406)-333-4434 EMIGRANT GENERAL STORE
PO BOX 60
EMIGRANT MT 59027-0060

Bert Otis, UST Class A Operator
Bert Otis, UST Class B Operator
Jason Otis, UST Class B Operator
Josh Otis, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	26	9/1/1989	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
4351			None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Galvanic
Gasoline		5/16/2013	Automatic Tank Gauging 0.2, Stat. Inventory Reconciliation	Not Listed	
6,000					
5	19	1/1/1997	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
4352			None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Galvanic
Gasoline		5/16/2013	Automatic Tank Gauging 0.2, Stat. Inventory Reconciliation	Continuous Interstitial Monitor	
10,000					
6	26	9/1/1989	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
4353			None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Galvanic
Diesel		5/16/2013	Automatic Tank Gauging 0.2, Stat. Inventory Reconciliation	Continuous Interstitial Monitor	
6,000					

Facility Summary in PARK County in the City of EMIGRANT

Location: COMMUNITY CONTINUITY INC
18 POLARIS WAY PARCEL 70 S GLASTONBURY
EMIGRANT, MT 59027 PARK

Sys Fac ID: 34-10930

Last Inspected On: 9/25/2014

Operating Permit Renewal Date: 10/2/2017

Contact: Walter Wunsch, (406) 333-4727

Owners/Operators: Community Continuity Inc, Owner (406)-333-4727 PO BOX 135
EMIGRANT MT 59027-0135

Daniel Kehoe Jr, UST Class A Operator

Daniel Kehoe Jr, UST Class B Operator

Dennis A Franks, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	26	2/1/1990	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
4821		9/25/2014	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Gravity Feed	Galvanic
Diesel		9/25/2014	Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
20,000			TLS-300 , Veeder Root		

Facility Summary in PARK County in the City of EMIGRANT

Location: COMMUNITY RESTORATION INC
HERCULES ROAD & POLARIS WAY
EMIGRANT, MT 59027 PARK

Sys Fac ID: 34-10931

Last Inspected On: 9/25/2014

Operating Permit Renewal Date: 10/2/2017

Contact: Daniel Kehoe Jr, (800) 631-8885

Owners/Operators: Community Restoration Inc, Owner (800)-631-8885 PO BOX 414
EMIGRANT MT 59027-0414

Daniel Kehoe Jr, UST Class A Operator

Daniel Kehoe Jr, UST Class B Operator

Dennis A Franks, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	26	2/20/1990	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
701		9/25/2014	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	U.S. Suction	Galvanic
Diesel		9/25/2014	Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
20,000			TLS-300 , Veeder Root		

Facility Summary in PARK County in the City of EMIGRANT

Location: SHELTER INVINCIBLE INC
25 GEMINI RD
EMIGRANT, MT 59027 PARK
Contact: Eleanor Schieffelin, (406) 333-4485

Sys Fac ID: 34-10933
Last Inspected On: 5/5/2014
Operating Permit Renewal Date: 8/24/2017

Owners/Operators: Shelter Invincible Inc, Owner (406)-333-4485 PO BOX 111
EMIGRANT MT 59027-0039
David Tonkin, UST Class A Operator
David Tonkin, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	25	4/17/1990	Cathodically Protected Steel	Copper	Flapper Valve (Auto Shutoff)
1882			None	Secondary Containment Chase	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Diesel		5/5/2014	Automatic Tank Gauging 0.2	Deferred	
2,000				Manual Interstitial Monitor	

Location:	COMMUNITY CONSERVATION ASSOCIATION PARCEL 2 N GLASTONBURY EMIGRANT, MT 59027 PARK			Sys Fac ID: 34-10934 Last Inspected On: 10/7/2013 Operating Permit Renewal Date: 12/11/2016	
Contact:	Ed Dratz, (406) 587-5667				
<hr/>					
Owners/Operators:	Community Conservation Association, Owner		(406)-579-3399	500 CONCORD DR BOZEMAN MT 59715-7120	
	Edward Dratz, UST Class A Operator				
	Edward Dratz, UST Class B Operator				
	Edward Dratz, UST Class B Global Operator				
Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	25	4/18/1990	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
4684			None	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Diesel		5/2/2014	Automatic Tank Gauging 0.2	Deferred	
12,000					

Facility Summary in PARK County in the City of EMIGRANT

Location: B BUNK INC
 PARCEL 38 N GLASTONBURY PO BOX 519
 EMIGRANT, MT 59027 PARK

Sys Fac ID: 34-10959

Last Inspected On: 1/6/2012

Operating Permit Renewal Date: 3/26/2018

Contact: Brad Tisdale, (406) 333-4512

Owners/Operators: B Bunk Inc, Owner

(757)-498-6060

3333 REGENT PARK WALK
 VIRGINIA BEACH VA 23452-6257

Bradford Tisdale, UST Class A Operator

Dennis A Franks, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	25	4/18/1990	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
415			None	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Diesel		10/15/2015	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
10,000			TLS-300 , Veeder Root		

Facility Summary in PARK County in the City of EMIGRANT

Location: MARKS ARK INC
 PARCEL #7 NORTH GLASTONBURY
 EMIGRANT, MT 59027 PARK

Sys Fac ID: 34-10960

Last Inspected On: 11/24/2014

Operating Permit Renewal Date: 1/6/2018

Contact: Philip Hoag, (406) 333-4707

Owners/Operators: Marks Ark Inc, Owner

(406)-333-4707

PO BOX 11
 EMIGRANT MT 59027-1626

Phillip Hoag, UST Class A Operator

Phillip Hoag, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	25	4/11/1990	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
1579			None	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Diesel		11/24/2014	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Deferred	
10,000					

Facility Summary in PARK County in the City of EMIGRANT

Location: LIFESAVERS INC
 LOT 28 NORTH GLASTONBURY PO BOX 56
 EMIGRANT, MT 59027 PARK

Sys Fac ID: 34-10965

Last Inspected On: 2/12/2016

Operating Permit Renewal Date:

Contact: Robert Smith, (406) 333-4387

Owners/Operators: Lifesavers Inc, Owner (406)-333-4213 PO BOX 211
 EMIGRANT MT 59027-0211

Patricia Jones, UST Class A Operator

Robert Smith, UST Class A Operator

Patricia Jones, UST Class B Operator

Robert Smith, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	25	4/1/1990	Cathodically Protected Steel	Steel	Flapper Valve (Auto Shutoff)
4499			None	Double-Walled	Yes
Temporarily Out of Use			Not Required	Pressurized	Galvanic
Diesel		8/11/2014	Vapor Monitoring	Vapor Monitoring, Continuous Interstitial Monitor	
12,000					

Facility Summary in PARK County in the City of EMIGRANT

Location: EARTH HOME PROPERTIES LLC
EVENING STAR DR
EMIGRANT, MT 59027 PARK

Sys Fac ID: 34-10978

Last Inspected On: 7/16/2013

Operating Permit Renewal Date:

Contact: Craig Newhouse, (978) 857-0002

Owners/Operators: Earth Home Properties LLC, Owner Craig Newhouse, Operator Craig Newhouse, UST Class A Operator Craig Newhouse, UST Class B Operator	(978)-658-7658 (978)-857-0002	5 EMMA WAY WILMINGTON MA 01887 EARTH HOME PROPERTIES LLC 5 EMMA WAY WILMINGTON MA 01887-2745
---	--------------------------------------	--

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	25	4/23/1990	Cathodically Protected Steel	No Piping	Flapper Valve (Auto Shutoff)
4754			None	None	Yes
Temporarily Out of Use			Not Required	Safe Suction	Galvanic
Diesel		9/3/2010	Vapor Monitoring		
10,000					
2	25	4/23/1990	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
4753			None	None	Yes
Temporarily Out of Use			Not Required	Safe Suction	Galvanic
Diesel		9/3/2010	Vapor Monitoring	Deferred	
12,000					

Facility Summary in PARK County in the City of EMIGRANT

Location: CAPSTONE SHELTER
 LOT 105 S GLASTONBURY
 EMIGRANT, MT 59027 PARK

Sys Fac ID: 34-10989

Last Inspected On: 10/25/2013

Operating Permit Renewal Date:

Contact: Enrico DArgenzio, (406) 333-4576

Owners/Operators: Capstone Project, Owner

(480)-657-2564

14449 N 99TH ST
 SCOTTSDALE AZ 85260-3835

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	25	4/13/1990	Cathodically Protected Steel	Steel	Ball Float Valve
4827			Double-Walled	Double-Walled	Yes
Temporarily Out of Use			Not Required	Pressurized	Galvanic
Diesel		10/25/2013	Vapor Monitoring, Continuous Interstitial Monitor	Vapor Monitoring	
12,000					

Facility Summary in PARK County in the City of EMIGRANT

Location: HELMET OF SALVATION SHELTER UST
65 ARCTURUS DR
EMIGRANT, MT 59027 PARK

Sys Fac ID: 34-13180

Last Inspected On: 3/15/2014

Operating Permit Renewal Date: 6/30/2017

Contact: Ken Mueller, (406) 333-4669

Owners/Operators: Helmet of Salvation Shelter Assoc, Owner

(406)-333-4669

PO BOX 419

EMIGRANT MT 59027-0419

Kenneth Mueller Jr, UST Class A Operator

Kenneth Mueller Jr, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	20	12/1/1995	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
3123			None	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Diesel		3/15/2014	Stat. Inventory Reconciliation	Not Listed	
10,000					

Facility Summary in PARK County in the City of EMIGRANT

Location: DENNIS CURTIN
70 RAMS HORN RD
EMIGRANT, MT 59027 PARK

Sys Fac ID: 56-14035

Last Inspected On: 11/6/2013

Operating Permit Renewal Date: 12/31/2016

Contact: (406) 333-4056

Owners/Operators: D M Curtin Family Limited Partnership, Owner (816)-459-7740 2860 NE KENDALLWOOD PKWY
KANSAS CITY MO 64119-2026
Channell T Libbey III, UST Class A Operator
Todd Fredericksen, UST Class B Operator
Dennis A Franks, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	14	10/15/2001	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
4435		11/29/2012	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel			Continuous Interstitial Monitor	Continuous Interstitial Monitor	
8,000					

Facility Summary in PARK County in the City of GARDINER

Location: TOWN STATION
220 PARK ST
GARDINER, MT 59030 PARK

Sys Fac ID: 34-02285

Last Inspected On: 7/16/2013

Operating Permit Renewal Date: 12/21/2016

Contact: Wade Laubach, (406) 848-7501

Owners/Operators: Gardiner Town Club Inc, Owner (406)-848-7501 PO BOX 990
GARDINER MT 59030-0990
Wade Laubach, UST Class A Operator
Wade Laubach, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	39	4/29/1976	Bare Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
3910			Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Gasoline		7/16/2013	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
6,000		7/16/2013			
2	39	4/29/1976	Bare Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
3911			Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Gasoline		7/16/2013	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
6,000		7/16/2013			
3	39	4/29/1976	Bare Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
3912			Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Gasoline		7/16/2013	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
6,000		7/16/2013			

Facility Summary in PARK County in the City of GARDINER

Location: TOWN STATION
220 PARK ST
GARDINER, MT 59030 PARK

Sys Fac ID: 34-02285

Last Inspected On: 7/16/2013

Operating Permit Renewal Date: 12/21/2016

Contact: Wade Laubach, (406) 848-7501

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
7	15	1/1/2001	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
4247			Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Diesel		7/16/2013	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
10,000		7/16/2013			

Facility Summary in PARK County in the City of GARDINER

Location: RANCH OFFICE
558 OLD YELLOWSTONE TRAIL SOUTH
GARDINER, MT 59030 PARK

Sys Fac ID: 34-03402

Last Inspected On: 7/8/2014

Operating Permit Renewal Date: 9/3/2017

Contact: David Otis, (406) 848-9043

Owners/Operators: Church Universal & Triumphant Inc, Owner (406)-848-9200 63 SUMMIT WAY
GARDINER MT 59030-9314

David Otis, UST Class A Operator

David Otis, UST Class B Operator

Steven Zacharias, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
7	27	10/21/1988	Cathodically Protected Steel	Steel	High Level Alarm
1861			None	none	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		7/8/2014	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
20,000		7/8/2014	TLS-350/Gilbarco EMC , Veeder Root		
8	27	10/21/1988	Cathodically Protected Steel	Steel	High Level Alarm
1862			None	none	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Diesel		7/8/2014	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
20,000		7/8/2014	TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in PARK County in the City of GARDINER

Location: KREMERS CENEX
401 SCOTT ST W PO BOX 507
GARDINER, MT 59030 PARK

Sys Fac ID: 34-06531

Last Inspected On: 2/25/2015

Operating Permit Renewal Date: 3/3/2018

Contact: Scott Kremer, (406) 848-7742

Owners/Operators: Kremer Brothers Inc, Owner

(406)-848-7742

DBA KREMERS CENEX
PO BOX 507
GARDINER MT 59030-0507

Scott Kremer, UST Class A Operator

Scott Kremer, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	31	4/16/1984	Bare Steel	Steel	Flapper Valve (Auto Shutoff)
3189			Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Gasoline		7/16/2013	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
8,000		2/5/2015	TLS-300 , Veeder Root		
2	31	4/16/1984	Bare Steel	Steel	Flapper Valve (Auto Shutoff)
3190			Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Gasoline		7/16/2013	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
4,000		2/5/2015	TLS-300 , Veeder Root		
3	31	4/16/1984	Bare Steel	Steel	Flapper Valve (Auto Shutoff)
3191			Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Diesel		7/16/2013	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
4,000		2/5/2015	TLS-300 , Veeder Root		

Facility Summary in PARK County in the City of GARDINER

Location: KREMERS CENEX
401 SCOTT ST W PO BOX 507
GARDINER, MT 59030 PARK

Sys Fac ID: 34-06531

Last Inspected On: 2/25/2015

Operating Permit Renewal Date: 3/3/2018

Contact: Scott Kremer, (406) 848-7742

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	31	4/16/1984	Bare Steel	Steel	Flapper Valve (Auto Shutoff)
3192			Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Gasoline		7/16/2013	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
8,000		2/5/2015	TLS-300 , Veeder Root		

Facility Summary in PARK County in the City of GARDINER

Location: GARDINER SERVICE CENTER
US HIGHWAY 89 S
GARDINER, MT 59030 PARK

Sys Fac ID: 34-08868

Last Inspected On: 4/16/2013

Operating Permit Renewal Date: 7/28/2016

Contact: Dylan Hoffman, (307) 344-5204

Owners/Operators: Xanterra Parks & Resorts Inc, Owner/Operator

(307)-344-5340

ATTN DYLAN HOFFMAN

PO BOX 165

YELLOWSTONE NATIONAL PARK WY 82190-0753

Johnny Duncan, UST Class A Operator

David Singleton, UST Class A Operator

David Singleton, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
6	19	4/1/1996	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
3492			Double-Walled	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Not Applicable
Gasoline			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor, Deferred	
10,000					
7	19	4/1/1996	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
3493			Double-Walled	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor, Deferred	
5,000					

Facility Summary in PARK County in the City of GARDINER

Location: GARDINER SCHOOL DIST 4

510 STONE ST

GARDINER, MT 59030 PARK

Sys Fac ID: 34-09287

Last Inspected On: 11/24/2014

Operating Permit Renewal Date: 1/2/2018

Contact: Lynn H Mavencamp, (406) 848-7563

Owners/Operators: School Dist 7 & 4 Gardiner Public, Owner

(406)-848-7563

510 STONE ST

GARDINER MT 59030-9378

Douglas F Coy, UST Class A Operator

Tom Nelson, UST Class A Operator

Douglas F Coy, UST Class B Operator

Tom Nelson, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	28	4/24/1987	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
4451		5/12/2015	None	Double-Walled	Yes
Currently in Use			Auto Dialer	Pressurized	Galvanic
Heating Oil		11/24/2014	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
8,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in PARK County in the City of LIVINGSTON

Location: Old Holiday Gas Station
1019 W PARK ST
LIVINGSTON, MT 59047 PARK

Sys Fac ID: 34-08071

Last Inspected On: 3/30/2015

Operating Permit Renewal Date:

Contact: David Amsk, (406) 222-3817

Owners/Operators: BVA 2 LLC, Owner (406)-222-3817 120 NORTH G STREET
LIVINGSTON MT 59047

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	40	10/1/1975	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
3031			Lined Interior/Impressed Current	None	Yes
Temporarily Out of Use		4/1/2008	Mechanical Line Leak Detector	Pressurized	Impressed Current
Gasoline		3/30/2015	Tank Tightness Testing, Stat. Inventory Reconciliation	Stat. Inventory Reconciliation, MLLD Line Tightness Testing	
12,000					
2	40	10/1/1975	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
3032			Lined Interior/Impressed Current	None	Yes
Temporarily Out of Use		4/1/2008	Mechanical Line Leak Detector	Pressurized	Impressed Current
Gasoline		3/30/2015	Tank Tightness Testing, Stat. Inventory Reconciliation	Stat. Inventory Reconciliation, MLLD Line Tightness Testing	
12,000					

Facility Summary in PARK County in the City of LIVINGSTON

Location: TOWN PUMP INC LIVINGSTON 2
29 N H ST
LIVINGSTON, MT 59047 PARK
Contact: Trent Biggers, (406) 497-6700

Sys Fac ID: 34-08713
Last Inspected On: 1/26/2016
Operating Permit Renewal Date: 4/2/2019

Owners/Operators: Park Casino, Owner (406)-497-6700 600 S MAIN ST
BUTTE MT 59701

Charles A Armstrong, UST Class A Operator
Trent Biggers, UST Class A Operator
Don Edmisten, UST Class A Operator
Charles A Armstrong, UST Class B Global Operator
Trent Biggers, UST Class B Global Operator
Don Edmisten, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	19	9/1/1996	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2577			Double-Walled	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline			Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000			Gilbarco EMC Basic , Gilbarco	Continuous Interstitial Monitor	
2	19	9/1/1996	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2578			Double-Walled	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Diesel			Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000			Gilbarco EMC Basic , Gilbarco	Continuous Interstitial Monitor	
5	19	9/1/1996	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2575			Double-Walled	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable, Not Applicable
Gasoline			Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000			Gilbarco EMC Basic , Gilbarco	Continuous Interstitial Monitor	

Facility Summary in PARK County in the City of LIVINGSTON

Location: TOWN PUMP INC LIVINGSTON 2
29 N H ST
LIVINGSTON, MT 59047 PARK

Sys Fac ID: 34-08713

Last Inspected On: 1/26/2016

Operating Permit Renewal Date: 4/2/2019

Contact: Trent Biggers, (406) 497-6700

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
6	19	9/1/1996	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2576			Double-Walled	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline			Continuous Interstitial Monitor, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000			Gilbarco EMC Basic , Gilbarco	Continuous Interstitial Monitor	

Facility Summary in PARK County in the City of LIVINGSTON

Location: QWEST LIVINGSTON CENTRAL OFFICE
302 W CALLENDER ST
LIVINGSTON, MT 59047 PARK

Sys Fac ID: 34-08777

Last Inspected On: 10/22/2014

Operating Permit Renewal Date: 3/20/2018

Contact: Kevin Robison, (801) 237-3006

Owners/Operators: Qwest Corporation, Owner	(801)-237-3006	250 E 200 S #1601 SALT LAKE CITY UT 84111
Qwest Corporation, Operator	(801)-237-3006	250 E 200 S #1601 SALT LAKE CITY UT 84111
Thomas J Pitts, UST Class A Operator		
Kevin Robison, UST Class A Operator		
Thomas J Pitts, UST Class B Operator		
Kevin Robison, UST Class B Operator		
Thomas J Pitts, UST Class B Global Operator		
Kevin Robison, UST Class B Global Operator		

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	58	4/15/1957	Concrete	Flexible Plastic	High Level Alarm
4811	Yes		Double-Walled	None	Yes
Currently in Use			Not Required	U.S. Suction	Not Applicable
Diesel		10/22/2014	Continuous Interstitial Monitor, Deferred	MLLD Line Tightness Testing	
275		12/8/2011			

Facility Summary in PARK County in the City of LIVINGSTON

Location: CASEYS #4
2050 SOUTH PARK
LIVINGSTON, MT 59047 PARK

Sys Fac ID: 34-09906

Last Inspected On: 6/27/2013

Operating Permit Renewal Date: 7/22/2016

Contact: Gary Scales, (406) 587-7438

Owners/Operators: Story Distributing Company, Owner (406)-587-0702 PO BOX 1201
BOZEMAN MT 59771
Jason Shanley, Operator (406)-587-0702 PO BOX 1201
BOZEMAN MT 59771-1201
Jason Shanley, UST Class A Operator
Venus Banthem, UST Class B Operator
Jason Shanley, UST Class B Operator
Kelly Scott Shutes, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
5	17	5/1/1998	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
2033			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		6/24/2013	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	
12,000					
6	17	5/1/1998	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
2034			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		6/24/2013	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	
12,000					
7	17	5/1/1998	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
2035			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Diesel		6/24/2013	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	
8,000					

Facility Summary in PARK County in the City of LIVINGSTON

Location: CITY COUNTY COMPLEX
414 E CALLENDER ST
LIVINGSTON, MT 59047 PARK

Sys Fac ID: 34-10573

Last Inspected On: 8/7/2013

Operating Permit Renewal Date: 10/1/2016

Contact: Dan Gutebier, (406) 222-4106

Owners/Operators: Park County Shop, Owner

(406)-222-4106

ATTN MAINT SUPV BRUCE
414 E CALLENDER ST
LIVINGSTON MT 59047-2700

Kelly Johnson, UST Class A Operator

Kelly Johnson, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	20	11/1/1995	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
1783			Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.1, Continuous Interstitial Monitor	Continuous Interstitial Monitor, MLLD Line Tightness Testing	
3,000		9/13/2013			

Facility Summary in PARK County in the City of LIVINGSTON

Location: YELLOWSTONE TRUCK STOP LIVINGSTON
1226 US HIGHWAY 10 W
LIVINGSTON, MT 59047 PARK

Sys Fac ID: 34-11200

Last Inspected On: 12/12/2013

Operating Permit Renewal Date: 3/25/2017

Contact: Carol Graybill, (406) 222-6180

Owners/Operators: Yellowstone Truck Stop Livingston, Owner (406)-222-2131 1226 US HIGHWAY 10 W
LIVINGSTON MT 59047-9004

Jerry Graybill, UST Class A Operator
Donald Burkenpas, UST Class B Operator
Jerry Graybill, UST Class B Operator
Stacey Lofing, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	27	1/1/1989	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
2313			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Diesel		12/12/2013	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
8,000					
2	27	1/1/1989	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
2314			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Diesel		12/12/2013	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
6,000					
3	27	1/1/1989	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
2315			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		12/12/2013	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
6,000					

Facility Summary in PARK County in the City of LIVINGSTON

Location: YELLOWSTONE TRUCK STOP LIVINGSTON
1226 US HIGHWAY 10 W
LIVINGSTON, MT 59047 PARK

Sys Fac ID: 34-11200

Last Inspected On: 12/12/2013

Operating Permit Renewal Date: 3/25/2017

Contact: Carol Graybill, (406) 222-6180

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	27	1/1/1989	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
2316			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		12/12/2013	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
6,000					

Facility Summary in PARK County in the City of LIVINGSTON

Location: ZIP TRIP 47
101 CENTENNIAL DR
LIVINGSTON, MT 59047 PARK

Sys Fac ID: 34-11741

Last Inspected On: 2/24/2015

Operating Permit Renewal Date: 3/9/2018

Contact: Todd Peterson, (406) 222-7371

Owners/Operators: CHS Inc - Spokane Valley, Owner (509)-535-7701 16124 E MARIETTA LANE
SPOKANE VALLEY WA 99216
Cenex Zip Trip, Operator (509)-535-7701 16124 E MARIETTA LANE
SPOKANE VALLEY WA 99216
Ian Johnstone, UST Class A Operator
Nicholas Merritt, UST Class B Operator
Darcy Ziegler, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	25	9/1/1990	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
562			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic, Not Applicable
Gasoline		9/2/2014	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
10,000		9/2/2014	TLS-350/Gilbarco EMC , Veeder Root		
2	25	9/1/1990	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
563			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic, Not Applicable
Gasoline		9/2/2014	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
10,000		9/2/2014	TLS-350/Gilbarco EMC , Veeder Root		
3	25	9/1/1990	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
564			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic, Not Applicable
Diesel		9/2/2014	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
10,000		9/2/2014	TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in PARK County in the City of LIVINGSTON

Location: TOWN PUMP INC LIVINGSTON 3
2200 PARK ST S
LIVINGSTON, MT 59047 PARK

Sys Fac ID: 34-13409

Last Inspected On: 2/22/2016

Operating Permit Renewal Date: 4/2/2016

Contact: Kevin Kenneally, (406) 222-5527

Owners/Operators: Livingston Holdings LLC, Owner (406)-497-6700 PO BOX 6000
BUTTE MT 59702-6000
Trent Biggers, UST Class A Operator
Trent Biggers, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	21	5/20/1994	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2579			Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Gasoline			Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000				Continuous Interstitial Monitor	
2	21	5/20/1994	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2580			Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Gasoline			Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000				Continuous Interstitial Monitor	
3	21	5/1/1994	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2581			Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel			Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000				Continuous Interstitial Monitor	
4	21	5/1/1994	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2582			Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel			Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000				Continuous Interstitial Monitor	

Facility Summary in PARK County in the City of LIVINGSTON

Location: TOWN PUMP INC LIVINGSTON 3
2200 PARK ST S
LIVINGSTON, MT 59047 PARK
Contact: Kevin Kenneally, (406) 222-5527

Sys Fac ID: 34-13409
Last Inspected On: 2/22/2016
Operating Permit Renewal Date: 4/2/2016

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
5	21	5/1/1994	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2583			Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel			Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000				Continuous Interstitial Monitor	
6	14	10/1/2001	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4377			Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel			Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
10,000				Continuous Interstitial Monitor	
7	14	10/1/2001	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4378			Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel			Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
5,000				Continuous Interstitial Monitor	
8	14	10/1/2001	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4379			Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Gasoline			Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000				Continuous Interstitial Monitor	

Facility Summary in PARK County in the City of LIVINGSTON

Location: TJS GAS N CONVENIENCE
204 W PARK ST
LIVINGSTON, MT 59047 PARK

Sys Fac ID: 34-13736

Last Inspected On: 7/1/2014

Operating Permit Renewal Date: 9/3/2017

Contact: Terry Ricci, (406) 222-9720

Owners/Operators: TJs Gas N Convenience, Owner (406)-222-9720 204 E PARK ST
LIVINGSTON MT 59047-2713
Terry Ricci, UST Class A Operator
Terry Ricci, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	19	5/1/1996	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
3371			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		7/1/2014	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
10,000			TLS-300 , Veeder Root	Continuous Interstitial Monitor	
2	19	5/1/1996	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
3372			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		7/1/2014	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
10,000			TLS-300 , Veeder Root	Continuous Interstitial Monitor	

Facility Summary in PARK County in the City of WILLSALL

Location: PARK FARMERS COOP
114 S ELLIOT
WILLSALL, MT 59086 PARK

Sys Fac ID: 34-06686

Last Inspected On: 2/11/2016

Operating Permit Renewal Date: 5/24/2019

Contact: Donald Scott, (406) 578-2543

Owners/Operators: Park Farmers Coop, Owner (406)-578-2543 PO BOX 129
WILLSALL MT 59086-0129
Donald Scott, Operator (406)-686-4489 19 ASPEN LN
CLYDE PARK MT 59018
Don Scott, UST Class A Operator
Don Scott, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
13	22	7/1/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1784			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline		4/26/2010	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
12,000		4/17/2013	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
14	22	7/1/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1785			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable, Not Applicable
Diesel		4/26/2010	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
12,000		4/17/2013	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
15	22	7/1/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1786			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable, Not Applicable
Gasoline		4/26/2010	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
6,000		4/17/2013	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

Facility Summary in PARK County in the City of WILLSALL

Location: PARK FARMERS COOP
114 S ELLIOT
WILLSALL, MT 59086 PARK

Sys Fac ID: 34-06686

Last Inspected On: 2/11/2016

Operating Permit Renewal Date: 5/24/2019

Contact: Donald Scott, (406) 578-2543

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
16	22	7/1/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1787			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable, Not Applicable
Diesel		4/26/2010	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
6,000		4/17/2013	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	